


Fire Safety Bond Measure



Fremont Fire Department: A History of Excellence



RESCUE



EMS



FIRE



HAZMAT₂

***EXCELLENT
SERVICE***

Recommended Bond Projects

- Replace Stations 2 (Niles), 6 (Centerville), and 8 (North Fremont)
- Make earthquake and safety improvements to remaining seven fire stations
- Construct Public Safety Training Center

Total Cost: \$51 million

Replace Station 2 (Niles)

37645 Second Street



Station built 1952.

Modern fire engines are too big for the garage.

Replace Station 2



Workout room is in garage.

Cramped quarters



Replace Station 6 (Centerville) 37412 Fremont Boulevard



Station built 1954.

Modern fire engines are too big for the garage.



Replace Station 6 (Centerville)



Small station = turnouts exposed to exhaust from fire engines.

Dry rot and termite damage to roof.



Replace Station 8 (North Fremont) 3723 Darwin Drive

Garage doors are too low.



35-year old “temporary” station.
Garage doubles as workout room.

What Does a Modern Station Look Like?



Station 9 (Stevenson Place)

Earthquake and Safety Improvements to Remaining Stations



Stations must be hubs of government following a disaster.



New Public Safety Training Center



Benefits to the Community



- Earthquake response improved
- Better trained staff
- Ability to grow with the population

There when you need us.